

	Type	Ref #	Hits	Search Text	DBs
1	BRS	S1	2222	((volt\$4 or bias\$3) same develop\$4 same contact same (switch\$3 or changeover)).detd.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
2	BRS	S2	0	"20050053391pn."	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
3	BRS	S3	0	"20050053391.pn."	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
4	BRS	S4	2	"20050053391".pn.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
5	BRS	S5	287	(high near2 (volt\$4 or bias\$3) same develop\$4 same contact same (switch\$3 or changeover)).detd.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
6	BRS	S6	60	S5 and develop\$4.ab.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
7	BRS	S10	1	"20050053391".pn. and fix\$3 near contact\$3 near point and develop\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
8	BRS	S7	1	"20050053391".pn. and fix\$3 near contact\$3 near point	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
9	BRS	S15	1	jip2001356553a	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
10	BRS	S12	1	(pwb or pcb) same (contact\$3 near5 develop\$4) and voltage near changeover	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
11	BRS	S11	1	"20050053391".pn. and (fix\$3 near contact\$3 near point and develop\$4 and voltage near changeover).detd.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
12	BRS	S9	2	"5051866".pn.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
13	BRS	S8	4	"5627722".pn. or "20020064390".pn.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
14	BRS	S13	205	(pwb or pcb or board) same (contact\$3 near5 develop\$4) and voltage	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB

	Time Stamp	Comments	Error Definition	Errors
1	2006/04/02 17:28			
2	2006/03/30 21:04			
3	2006/03/30 21:05			
4	2006/03/30 21:05			
5	2006/03/30 21:18			
6	2006/03/30 21:19			
7	2006/04/03 11:42			
8	2006/04/03 11:35			
9	2006/04/03 12:19			
10	2006/04/03 12:04			
11	2006/04/03 12:02			
12	2006/04/03 11:25			
13	2006/04/03 11:25			
14	2006/04/03 12:05			

	Type	Ref #	Hits	Search Text	DBs
15	BRS	S14	57	S13 and develop\$4.ab.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
16	BRS	S16	2	"20020064390".pn.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
17	BRS	S17	1	"20020064390".pn. and (develop\$3 same blade same volt\$4).detd.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
18	BRS	S18	1	"20020064390".pn. and (circuit).detd.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
19	BRS	S19	0	single near2 volt\$4 same develop\$3 same supply\$3 near roll\$3 same blade	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
20	BRS	S20	400	volt\$4 same (develop\$3 same supply\$3 near roll\$3 same blade)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
21	BRS	S24	1	"20050053391".pn. and 319a	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
22	BRS	S25	1	"20050053391".pn. and 320a	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
23	BRS	S26	0	"20050053391".pn. and 325a	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
24	BRS	S27	1	"20050053391".pn. and 317a	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
25	BRS	S28	1	"20050053391".pn. and 315a	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
26	BRS	S29	1	"20050053391".pn. and 305a	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
27	BRS	S21	23	volt\$4 near (source or circuit) same (develop\$3 same supply\$3 near roll\$3 same blade)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
28	BRS	S22	0	"20050053391".pn. and volt\$4 near (source or circuit) same (develop\$3 same supply\$3 near roll\$3 same blade)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB

	Time Stamp	Comments	Error Definition	Errors
15	2006/04/03 12:18			
16	2006/09/11 12:01			
17	2006/09/11 12:10			
18	2006/09/11 12:11			
19	2006/09/11 12:14			
20	2006/09/11 12:15			
21	2006/09/11 12:40			
22	2006/09/11 12:41			
23	2006/09/11 12:41			
24	2006/09/11 12:42			
25	2006/09/11 12:42			
26	2006/09/11 12:43			
27	2006/09/11 12:31			
28	2006/09/11 12:32			

	Type	Ref #	Hits	Search Text	DBs
29	BRS	S23	1	"20050053391".pn. and volt\$4 near (source or circuit) and (supply\$3 and roll\$3 and blade)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB
30	BRS	S30	1	"20050053391".pn. and 309a	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB

	Time Stamp	Comments	Error Definition	Errors
29	2006/09/11 12:39			
30	2006/09/11 12:43			